
FORM B - BUILDING

MASSACHUSETTS HISTORICAL COMMISSION MASSACHUSETTS ARCHIVES BUILDING 220 MORRISSEY BOULEVARD BOSTON, MASSACHUSETTS 02125

Photograph



Topographic or Assessor's Map



Recorded by: Lisa Mausolf

Organization: Lexington Historical Commission

Date (month / year): May 2008

		()	
13/404	Boston North		

USGS Ouad Area(s) Form Number

Town: Lexington

Assessor's Number

Place: (neighborhood or village)

East Lexington

Address: 72 Bow Street (at Melrose Ave.)

Historic Name: William Waite House

Uses: Present: residential

Original: residential

Date of Construction: c.1920

Source: directories

Style/Form: Colonial (Dutch) Revival

Architect/Builder: unknown

Exterior Material:

Foundation: concrete block

Wall/Trim: vinyl siding

Roof: asphalt shingles

Outbuildings/Secondary Structures:

garage

Major Alterations (with dates):

date? - vinyl siding, new windows, deck

Condition: fair (due to siding)

Moved: no | x | yes | | Date _____

Acreage: 0.21 acre

Setting: mixed residential neighborhood

INVENTORY FORM B CONTINUATION SHEET

LEXINGTON

72	BO	W	ST	R)	EE'	

MASSACHUSETTS HISTORICAL COMMISSION 220 MORRISSEY BOULEVARD, BOSTON, MASSACHUSETTS 02125

Area(s)	Form No.	
l .		

Recommended for listing in the National Register of Historic Places.	
If checked, you must attach a completed National Register Criteria Statement form.	
9	

ARCHITECTURAL DESCRIPTION:

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings within the community.

The house at 72 Bow Street is one of several gambrel-fronted dwellings in this neighborhood and was built according to the same plan as its neighbor at 68 Bow Street. Sheathed in vinyl siding, the house rests on a rusticated concrete block foundation. It is two-stories in height with a sidehall entry containing a wooden and oval glass door sheltered by a simple gable door hood. Adjacent to the entrance is a single-story, three-sided bay window. A similar bay window is also located on the south elevation. Windows contain 1/1 replacement sash.

To the west of the house is a detached, hip-roofed garage constructed of rusticated concrete blocks with two modern garage doors facing Melrose Avenue.

HISTORICAL NARRATIVE

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

This property was lots 33-35 of the Massachusetts Avenue Terrace subdivision laid out by J.W. Wilbur in 1909 (Plan Book 182, Plan 8). This is one of several subdivisions that Wilbur, who lived in Brookline, developed in East Lexington in the early 20th century. What is now Bow Street, was originally known as Wilson Avenue.

The earliest known owner was William Waite who was living here by 1930. He was the manager of a fish business. His wife Hanna had come to this country from Sweden. The couple was still living here in 1942. The property was purchased by Alexander Liazos in 1973.

BIBLIOGRAPHY and/or REFERENCES

Middlesex South Registry of Deeds, Cambridge, Mass. Town Directories U.S. Census, various years.

INVENTORY FORM B CONTINUATION SHEET

LEXINGTON

72 BOW STREET

MASSACHUSETTS HISTORICAL COMMISSION 220 MORRISSEY BOULEVARD, BOSTON, MASSACHUSETTS 02125

Area(s)	Form No.

